TENNESSEE DEPARTMENT OF TRANSPORTATION EROSION PREVENTION/SEDIMENT CONTROL INSPECTION REPORT

TDOT EPSC INSPECTION FORM Rev. Feb 2010

Reason For Inspection:

1st Weekly

2nd Weekly

											DATE: /2.	1.11	
State Route	(SR) / US Rot	ite or Road Na	ame and De	escription:			Are correcti	ve actions	required by	lhis inspec	tion report (Y/N):		
		Wolf	River Blvd.										
County(ies)	:	TDOT PIN:		NPDES Pe	rmit (NOC)	#:	Number of New Number of Recurring			Number of New	Number of U	Jn-Corrected	
SI	relby	1016	15	٦	TNR153299)	Corrective /	Actions:	Corrective A	Actions:	Sediment Releases	: Sediment Re	eleases:
TDOT Cons	Iruction No.:	TDOT Contra	ct No.:	Contractor:			0		2				
7994-	1535-54			Acuff	Enterprises	s Inc.							
prepared und designed to a information p manage the information, of erosion an above. I cer identified out recorded in t	er penalty of law der my direction of assure that qualifaces ented. Based system, or those I cerify that inspend sediment contify that erosion at tall where install the table above talse information, alions.	or supervision in lied personnel part of a my inquiry persons directled colons of storm rols have been and sediment colons ed as planned sed l am aware that	n accordance properly gath of the person y responsible water dische performed a pulrols in the and designed there are significant.	e with a syste ered and eva n or persons e for gatherin arge points (o s recorded in drainage are I in working o	em sluated who sg the putfalls), and the table ea of the order as	Contractor	EPSC Inspect C Project Marpe):	ld "Jerry" S eclor and T Tom Acuff	tanfill ille (print or		Signature: Signature: Signature:	Starfie Out	ès.
<u></u>		TDOT EPSO						r =					
Date	Day of Week	Predicted Precipitation (%)	Rainfall Gauge 1 (in)	Rainfall Gauge 2 (in)	Rainfall Gauge 3 (in)	Rainfall Gauge 4 (in)	Rainfall Gauge 5 (in)	Rainfall Gauge 6 (in)	Duration (hr)	NO	ntractor Agrees with or YES ain and initial:	Inspection Re	porl:
	Sunday		· · · · · · · · · · · · · · · · · · ·		N/A	N/A	N/A	N/A	1		Half come	elimon	dal bonne
11.28.11	Monday	70	2.02	2.00	N/A	N/A	N/A	N/A	60.0	- U-41	made.	and and	1 .
11.29.11	Tuesday	20	0.28	0.30	N/A	N/A	N/A	N/A	7.0	.30	ristlall con	portions	and bearing
11.30.11	Wednesday	0			N/A	N/A	N/A	N/A		1	and Ride		7
12-1-11	Thursday	0	0	0	N/A	N/A	N/A	N/A		,			

Predicted Precipitation Source:

0

0

0

10

50

Friday

Saturday

Sunday

Monday

12.4.11

www.wealher.com

N/A

NIA

N/A

N/A

N/A

N/A

N/A

Page 1 of 7

(Additional pages may be attached, if needed)

نزد	OF TH	E 57%	ė.
		TURE	
	Dec.	1	
1/3	4 179	6 35	<i>!</i>

State/US Route or Road Name:	Wolf River Blvd.	TDOT Construction No.:	79954-3537-54	TDOT Contract No.:
		A CONTRACTOR OF THE CONTRACTOR		

Date	12/1/201	1

Outfall Name	Rain	Approx.	LT, RT or	Date Last	Date of Stabilization	Existing EPSC	Current	
or Station No.	Gage	Station No.	Centerline	Disturbed	and Code	Control	Condition	Corrective Action(s) or Comments
	No.	From / To			T = Temp.	Measure	Codes*	
					P = Perm.	Codes*		
								Weekly cleaning will be required, until further
1	1	14+14	LT	12/1/2011		22,35	FM	notice.
								RCBC Pedestrian Underpass/ No activity
1A	1	21+50	RT	11/17/2011		41	FM	during this inspection.
						ogo.		No activity during this inspection. Monitoring
1B	1	22+00	RT	11/10/2011		41	FM	BMP's in place.
1C	1	21+00	LT	11/7/2011	T = 10-6-11	12,15,35,41	FM	Monitoring BMP's in place.
2A	1	33+50	LT,CL	12/1/2011		12,15,16,24	FM	Monitoring BMP's in place.
2/		33+30	LI,OL	12/1/2011	· · · · · · · · · · · · · · · · · · ·	12,15,16,24	FIVI	
2B	1	35+50	LT	12/1/2011		16,24	FM	Weekly cleaning for stream crossing required, until further notice.
3	1	34+50	LT	10/27/2011		16	W	Monitoring BMP in place.
	4	40.00	-	44/7/0044	T 40.04.44	45.40.40		Repair wash out area. See 11-25-11 report
4	1	40+00	RT	11/7/2011	T = 10-24-11	15,16,43	I,RO	for photo.
5A	1	49+00	RT	12/1/2011	West	16,33	FM	Corrections made monitoring BMP's.
5B	1	50+00	RT	12/1/2011		9,16,33	FM	Corrections made monitoring BMP's.

EROSION AND SEDIMENT CONTROL MEASURE CODES

1	Temporary Silt Fence / Filter Barrier	15	Temporary seeding with Mulch	29	Excess Dirt Removed from Rdwy. Daily	М	Maintenance
2	Temporary Diversion Berm or Ditch	16	Temporary Mulch	30	Haul Roads Dampened for Dust Control	U	Upgrade Needed (Failure Noted)
3	Temporary Slope Drain	17	Erosion Control Blanket	31	Ditch Liner	R	Replacement Needed
4	Rock Check Dams	18	Flexible Channel Liner	32	Rock Silt Screen	FM	Future Maintenance
5	Brush Barrier	19	Catch Basin / Storm Inlet Protection	33	Temporary Silt Fence with Backing	С	Cleaning Needed
6	Sediment Removal	20	Riprap Outlet Structure	34	Enhanced Silt Fence	1	Increase Measures
7	Straw Bale Check	21	Riprap Energy / Velocity Dissipater	35	Sediment Tube	W	Too Wet to Work Conditions
8	Sand Bags	22	Curb, Gutter, or Storm Sewer Protection	36	Sediment Dam	RO	Repeat Occurrence
9	Sediment Trap / Basin	23	Temporary at Construction Exit / Entrance	37	Concrete Washout, other pollution Issues	SR	Sediment Release
10	Temp Sediment Filter Bag / Dewatering	24	Temporary Stream Crossing	38	Berm (soil, riprap, rock)	FS	Final Stabilized
11	Polyethylene Sheeting	25	Turbidity Barrier / Silt Boom	39	Gabion	S	Stable (No Action Needed)
12	Machined Rip Rap	26	Temporary Stream Diversion	40	Sheet Pilling	Other (O31):	
13	Geotextile	27	Preserve Natural Resource / Buffer Zone	41	Haul Road	Other (O#2):	
14	Permanent Seeding with Mulch or Sod	28	Mineral Aggregate Base on Subgrade	42	Bridge Construction		
				43	Stream Realignment		

CONDITION CODES

Ctoto/IIC	Davida		Dand	Name
State/US	Route	OI	Roau	Name

Wolf River Blvd.

TDOT Construction No.: 79954-3537-54

TDOT Contract No.:

Date _____12/1/2011

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stabilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
5C	1	44+00	LT	12/1/2011		16,24,33	I,RO	Weekly cleaning for stream crossing required. A section of BMP's needs to be completed along top of north and south bank @ New Channel Realignment. See Photo.
6	1	56+00	LT	12/1/2011		10-10-10-10-10-10-10-10-10-10-10-10-10-1	FM	Pond being drained during inspection. Currently Stable.
7	1	60+00	RT	10/24/2011		16, 33	FM	Currently Stable, Monitoring BMP's.
8A	1	73+00	RT	12/1/2011		16,24,42	FM	Weekly cleaning for stream crossing will be required, until further notice.
8B	2	75+50	RT	9/29/2011		16,24,35,41	FM	Currently Stable, Monitoring BMP's.
8C	1	71+00	LT	12/1/2011		16,35,42	FM	Bridge construction zone. Monitoring BMP's.
8D	2	75+50	LT	10/3/2011	T = 10-3-11	16,35,42	FM	Bridge construction zone. Monitoring BMP's.
8E	1	71+50	LT					The area has not been disturbed.
9A	2	80+00	RT	9/29//11	T = 10-3-11	6,15,33,35	FM	Weekly watering required until seed establishes.
9B	2	80+00	LT	9/29//11	T = 10-3-11	15,16,17,,35	FM	Weekly watering required until seed establishes.

EROSION AND SEDIMENT CONTROL MEASURE CODES

Temporary Silt Fence / Filter Barrier Excess Dirt Removed from Rdwy. Daily Maintenance Temporary Seeding with Mulch M 2 Temporary Diversion Berm or Ditch 16 Temporary Mulch 30 Haul Roads Dampened for Dust Control U Upgrade Needed (Failure Noted) Temporary Slope Drain Ditch Liner Replacement Needed 3 17 **Erosion Control Blanket** 31 Rock Check Dams 18 Flexible Channel Liner 32 Rock Silt Screen FM **Future Maintenance** Brush Barrier 5 19 Catch Basin / Storm Inlet Protection 33 Temporary Silt Fence with Backing C Cleaning Needed Sediment Removal **Enhanced Silt Fence** Riprap Outlet Structure Increase Measures 6 20 34 Straw Bale Check 21 Riprap Energy / Velocity Dissipater 35 Sediment Tube W Too Wet to Work Conditions 8 Sand Bags 22 Curb, Gutter, or Storm Sewer Protection 36 Sediment Dam RO Repeat Occurrence Sediment Trap / Basin Temporary at Construction Exit / Entrance Concrete Washout, other pollution Issues SR Sediment Release 9 23 37 10 Temp Sediment Filter Bag / Dewatering 24 Temporary Stream Crossing 38 Berm (soil, riprap, rock) Final Stabilized Polyethylene Sheeting 39 Gabion S 11 25 Turbidity Barrier / Silt Boom Stable (No Action Needed) Other (O31): 12 Machined Rip Rap 26 Temporary Stream Diversion 40 Sheet Pilling 13 Geotextile 27 Preserve Natural Resource / Buffer Zone 41 Haul Road Other (O#2): Other (O#3): Permanent Seeding with Mulch or Sod Mineral Aggregate Base on Subgrade **Bridge Construction**

EPSC Inspection

Page 3 of 7

CONDITION CODES

CALANTIC	Route or Roa	J \$1
olale/Uo	KOULE OF KOS	o manne.

Wolf River Blvd.

TDOT Construction No.:

79954-3537-54

TDOT Contract No.:

Date 12/1/2011

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stabilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
			11000					
9C	2	79+50	LT	9/29/2011	T = 10-03-11	15,16,20,33	FM	Weekly watering required until seed establishes.
10A	2	85+00	RT	9/29/2011		15,16,35,41	FM	Monitoring BMP's in place.
10B	2	85+00	RT	9/29/2011		15,16,35,41	FM	Monitoring BMP's in place.
10C	2	85+50	LT	11/14/2011		15,16,35,41	FM	Monitoring BMP's in place.
10D	2	84+50	LT	11/14/2011		15,16,35,41	FM	Monitoring BMP's in place.
11A	2	92+50	RT	11/14/2011		35,41	FM	Monitoring BMP's in place.
11B	2	92+50	LT	10/6/2011		10,32,35,41	W	Remove forms when accessible.
11C	2	92+00	LT	10/6/2011		10,32,35,41	W	Remove forms when accessible.
	1	11+28	LT	12/1/2011		19,35	FM	Daily cleaning is required, until further notice.
	1	13+40	RT	12/1/2011		23,29,30	FM	Daily cleaning will be required, until further notice.
	1	107+75	CL CL	12/1/2011	TACUPE CODES	23,29,30	FM	Daily cleaning will be required, until further notice.
		EKOSIOI	A WIAD SEDIME	IN I CONTROL IN	IEASURE CODES			CONDITION CODES

EROSION AND SEDIMENT CONTROL MEASURE CODES

Temporary Silt Fence / Filter Barrier Temporary Seeding with Mulch Excess Dirt Removed from Rdwy. Daily Maintenance M Temporary Diversion Berm or Ditch 2 16 Temporary Mulch 30 Haul Roads Dampened for Dust Control U Upgrade Needed (Failure Noted) Temporary Slope Drain 3 17 **Erosion Control Blanket** 31 Ditch Liner R Replacement Needed Rock Check Dams 18 4 Flexible Channel Liner 32 Rock Silt Screen FM **Future Maintenance** 5 Brush Barrier 19 Catch Basin / Storm Inlet Protection 33 Temporary Silt Fence with Backing C Cleaning Needed 6 Sediment Removal 20 Riprap Outlet Structure 34 **Enhanced Silt Fence** Increase Measures 7 Straw Bale Check 21 Riprap Energy / Velocity Dissipater 35 Sediment Tube W Too Wet to Work Conditions 8 Sand Bags 22 Curb, Gutter, or Storm Sewer Protection Sediment Dam 36 RO Repeat Occurrence Sediment Trap / Basin 9 23 Temporary at Construction Exit / Entrance 37 Concrete Washout, other pollution Issues SR Sediment Release 10 Temp Sediment Filter Bag / Dewatering 24 **Temporary Stream Crossing** 38 Berm (soil, riprap, rock) FS Final Stabilized Polyethylene Sheeting 11 25 Turbidity Barrier / Silt Boom 39 Gabion S Stable (No Action Needed) Machined Rip Rap 12 26 Temporary Stream Diversion 40 Sheet Pilling Other (O31): 13 Geotextile 27 Preserve Natural Resource / Buffer Zone 41 Haul Road Other (O#2): 14 Permanent Seeding with Mulch or Sod 28 Mineral Aggregate Base on Subgrade **Bridge Construction** Other (O#3):

SOTTHE STA	State
AGRICULTURE	
Commerce All	

State/US Route or Road Name:	Wolf River Blvd.	TDOT Construction No.:	79954-3537-54	TDOT Contract No.:	

Date	12/1/2011	

					Date of	Existing		
Outfall Name	Rain	Approx.	LT, RT or	Date Last	Stabilization	EPSC	Current	
or Station No.	Gage	Station No.	Centerline	Disturbed	and Code	Control	Condition	Corrective Action(s) or Comments
(Existing	No.	From / To			T = Temp.	Measure	Codes	
Structure)					P = Perm.	Codes*		
								Daily cleaning will be required, until further
* 109+51	2	East side of WRB	RT	12/1/2011		19,22	FM	notice.
		South side of						Daily cleaning will be required, until further
* 109+11	2	Farmington	RT	12/1/2011	- pq	19,22	FM	notice.
		North side of		**************************************		A2004 Dec 200000	20-20-20	Daily cleaning will be required, until further
* 12+80	1	WRB	LT	12/1/2011		19,22	FM	notice.
		Walking Trail				Second and the second s	NOV VARAMESS	13H 55594
	11	36+00	LT	7/20/2011	T = 7-20-11	5,35	FM	Currently stable, Monitoring BMP's
	1	Sta. 29+50 Slope	LT	7/20/2011	T= 9-01-11	16	FM	Currently stable.
		Sta. 13+40 -			- 8.462 8-544		200000000000000000000000000000000000000	Haul roads dampened frequently for dust
		Sta. 107+75	LT, RT or CL	10/13/2011		30	FM	control, until further notice.
				2				
1-11	2	76+50 - 103+46	RT	9/29/2011	T = 10-03-11	15,16,35	FM	Weekly watering required until seed establishes.
(5) (5) (5) (5) (5)		NAMES INVESTIGATE PROTECTION VANCOUS			50 00 00 00 00 00 00 00 00 00 00 00 00 0		52, 50000	
	2	92+50 - 107+00	LT	9/29/2011	T = 10-03-11	15,16,35	FM	Weekly watering required until seed establishes.
		2 0369		3				Daily cleaning will be required, until further
	1	6+75	LT	12/1/2011		19,22	FM	notice.
	1	27+00	RT	10/3/2011	T= 10-03-11	15,16	FM	Currently stable, Monitoring BMP's
	1	34+00	RT	8/25/2011	T= 8-25-11	16	FM	Currently stable, Monitoring BMP's
EROSION AND SEDIMENT CONTROL MEASURE CODES CONDITION CODES								

EROSION AND SEDIMENT CONTROL MEASURE CODES

1	Temporary Silt Fence / Filter Barrier	15	Temporary Seeding with Mulch	29	Excess Dirt Removed from Rdwy. Daily	М	Maintenance
2	Temporary Diversion Berm or Ditch	16	Temporary Mulch	30	Haul Roads Dampened for Dust Control	U	Upgrade Needed (Failure Noted)
3	Temporary Slope Drain	17	Erosion Control Blanket	31	Ditch Liner	R	Replacement Needed
4	Rock Check Dams	18	Flexible Channel Liner	32	Rock Silt Screen	FM	Future Maintenance
5	Brush Barrier	19	Catch Basin / Storm Inlet Protection	33	Temporary Silt Fence with Backing	С	Cleaning Needed
6	Sediment Removal	20	Riprap Outlet Structure	34	Enhanced Silt Fence	Ī	Increase Measures
7	Straw Bale Check	21	Riprap Energy / Velocity Dissipater	35	Sediment Tube	w	Too Wet to Work Conditions
8	Sand Bags	22	Curb, Gutter, or Storm Sewer Protection	36	Sediment Dam	RO	Repeat Occurrence
9	Sediment Trap / Basin	23	Temporary at Construction Exit / Entrance	37	Concrete Washout, other pollution Issues	SR	Sediment Release
10	Temp Sediment Filter Bag / Dewatering	24	Temporary Stream Crossing	38	Berm (soil, riprap, rock)	FS	Final Stabilized
11	Polyethylene Sheeting	25	Turbidity Barrier / Silt Boom	39	Gabion	S	Stable (No Action Needed)
12	Machined Rip Rap	26	Temporary Stream Diversion	40	Sheet Pilling	Other (O31):	890
13	Geotextile	27	Preserve Natural Resource / Buffer Zone	41	Haul Road	Other (O#2):	
14	Permanent Seeding with Mulch or Sod	28	Mineral Aggregate Base on Subgrade	42	Bridge Construction	Other (O#3):	

EPSC Inspection



0 id Name:	Wolf River Blvd.	TDOT Construction No.:	79954-3537-54	TDOT Contract No.:
		No.		

Date 12/1/2011

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stabilization and Code T = Temp.	Existing EPSC Control Measure	Current Condition Codes*	Corrective Action(s) or Comments
					P = Perm.	Codes*	Oddes	
	,	24 : 22 . 22 : 22		40/40/0044		(= 10.0= 1.1	2282	Weekly watering required until seed
	1	21+33 - 26+00	LT	10/10/2011	T = 10-6-11	15,16,35,41	FM	establishes.
	1	21+33 - 26+00	RT	10/10/2011	T = 10-6-11	15,16,35,41	FM	Weekly watering required until seed establishes.
	1	25+00	LT	9/29/2011	T = 10-6-11	15,16,33,35,41	FM	Currently stable, monitoring BMP's.
	1	25+00	RT	9/29/2011	T = 10-6-11	15,16,33,35,41	FM	Currently stable, monitoring BMP's.
	1	27+50	RT	10/6/2011	T = 10-6-11	15,16,33,35,41	FM	Currently stable, monitoring BMP's.
	1	31+90	RT	9/29/2011	T = 10-6-11	15,16,35	FM	Currently stable, monitoring BMP's.
1022120110	1	15+60	RT	9/15/2011	T = 10-6-11	15,16,33,35	FM	Currently stable, monitoring BMP's. Weekly watering required until seed establishes.
* 108+37		North side of WRB	LT	12/1/2011	900 H 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	19,22	FM	Daily cleaning will be required, until further notice.
	1	23+00 - 26+00	RT	9/29/2011	T = 10-6-11	33,41	FM	Currently stable, monitoring BMP's.
				2000 NOV				

EROSION AND SEDIMENT CONTROL MEASURE CODES

Temporary Silt Fence / Filter Barrier Temporary Seeding with Mulch 29 Excess Dirt Removed from Rdwy, Daily Maintenance Temporary Diversion Berm or Ditch 2 16 Temporary Mulch 30 Haul Roads Dampened for Dust Control U Upgrade Needed (Failure Noted) 3 Temporary Slope Drain 17 Erosion Control Blanket 31 Ditch Liner Replacement Needed Rock Check Dams 18 Flexible Channel Liner 32 Rock Silt Screen FM Future Maintenance **Brush Barrier** 19 Catch Basin / Storm Inlet Protection 33 Temporary Silt Fence with Backing C Cleaning Needed Sediment Removal 20 Riprap Outlet Structure Enhanced Silt Fence 34 Increase Measures Straw Bale Check 35 21 Riprap Energy / Velocity Dissipater Sediment Tube W Too Wet to Work Conditions Sand Bags 22 Curb, Gutter, or Storm Sewer Protection Sediment Dam 36 RO Repeat Occurrence 9 Sediment Trap / Basin 23 Temporary at Construction Exit / Entrance 37 Concrete Washout, other pollution Issues SR Sediment Release 10 Temp Sediment Filter Bag / Dewatering 24 Temporary Stream Crossing 38 Berm (soil, riprap, rock) FS Final Stabilized 11 Polyethylene Sheeting 25 Turbidity Barrier / Silt Boom 39 Gabion S Stable (No Action Needed) 12 Machined Rip Rap 26 Temporary Stream Diversion 40 Sheet Pilling Other (O31): ____ 13 Geotextile 27 Preserve Natural Resource / Buffer Zone 41 Haul Road Other (O#2): Permanent Seeding with Mulch or Sod 28 Mineral Aggregate Base on Sub grade **Bridge Construction** Other (O#3):

CONDITION CODES



Outfall 5C Sta. 44+00 LT A section of BMP's needs to be completed along top of north and south banks @ New Channel Realignment. (I.RO)

No Picture

